

*7136 7476*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> E-4587	<b>LOCATION</b> 618 - 24th Street				A-2
<b>DATE</b> Jul-31-63	<b>PURPOSE</b> Repair stairs & dwelling.				
<b>ZONE</b> R-1	<b>OWNER</b> E. Machado		601 - T Street		
	<b>ARCH'T</b>		GI 2-5624		
	<b>CONT'R</b> Chas. Vanina 2022 - Capitol Ave.				
<b>VAL.</b> \$500.		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>	<i>8-21-63</i>	<i>George K. ...</i>			

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>