

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-26370</i>	LOCATION <i>925 - 38th street</i>			
DATE <i>10-24-49</i>	PURPOSE <i>Re-roof</i>			
ZONE	OWNER <i>R.E. Mungier</i>			
	ARCH'T.			
	CON'TR. <i>Yancy Co</i>			
VAL. <i>\$ 290</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS

**COMPLETE
AND O. K.**

INSPECTOR

