

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-2896</i>	LOCATION <i>913 - 3<sup>rd</sup> St</i>			
DATE <i>May 15-10</i>	PURPOSE <i>Repairs to restaurant</i>			
ZONE	OWNER <i>Jang Quin</i>			
	ARCH'T.			
	CONTR. <i>A-1-Const. Co.</i>			
VAL. <i>700<sup>00</sup> =</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK-REMARKS
5/24/50	Frame Insp. (Rr. Sect. - Lower Floor) V. E. Buckius
5/26/50	Lath Insp. (Rr. Sect. - Low. Fl.) "
6/15/50	Final "
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>