

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|------------------------------|--|
| PERMIT NO. <i>B-16598</i> | LOCATION <i>5315 - E. St.</i> |
| DATE <i>7/10/46</i> | PURPOSE <i>Erect new dwlg. & garage</i> |
| ZONE | OWNER <i>W. J. Keenan</i> |
| | ARCH'T. |
| | CON'T'R. <i>James Jansen</i> |

| | | | | |
|-------------------------------|---------------------|-------------------|-------------------------|------|
| VAL. <i>7500⁰⁰</i> | STORIES <i>2</i> | ROOMS <i>5</i> | APTS. | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | <i>912⁰¹</i> | |
| VENT SHAFTS | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | | |
| LATH | | GAS VENTS | | |
| FIRE ESCAPES | | CHIMNEYS | | |
| STAND PIPES | | SKYLIGHTS | | |

| DATE | CONDITION OF WORK-REMARKS |
|----------|---|
| 9/19/46 | Form Insp. D. E. Buckner |
| 11/29/46 | Frame " " |
| 12/20/46 | Lath " " |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p> |