

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|------------------------------|---|
| PERMIT NO. <i>B-13368</i> | LOCATION <i>5024-10th Ave</i> |
| DATE <i>5/21/45</i> | PURPOSE <i>Repairs to dwg. fire loss</i> |
| ZONE | OWNER <i>Mrs J. Colgan</i> |
| | ARCH'T. |
| | CONTR. <i>Chas Tanen</i> |

| | | | | |
|-------------------------------|---------|-------|------------------|------|
| VAL. <i>2500⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
| LIGHT SHAFTS | | | ELEVATOR SHAFTS | |
| VENT SHAFTS | | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | | SPRINKLER SYSTEM | |
| LATH | | | GAS VENTS | |
| FIRE ESCAPES | | | CHIMNEYS | |
| STAND PIPES | | | SKYLIGHTS | |

| DATE | CONDITION OF WORK-REMARKS |
|------|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND O. K. INSPECTOR |