

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>13-6855</i>	LOCATION <i>3455 - 1st</i>			
DATE <i>10/29/40</i>	PURPOSE <i>Re-shingled roof fully.</i>			
ZONE	OWNER <i>Ella R. Campbell</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>200⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS

**COMPLETE
AND O. K.**

INSPECTOR

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-6855</i>	LOCATION <i>3455 J St</i>			
DATE <i>10/29/40</i>	PURPOSE <i>Reshingle Roof of Dwlg</i>			
ZONE <i>Multi-Fam</i>	OWNER <i>ELLA R. CAMPBELL, same</i>			
	ARCH'T.			
	CONT'R. <i>OWNER (day-work)</i>			
VAL. <i>200⁰⁰</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="308 854 436 896">COMPLETE AND O. K.</p> <p data-bbox="1169 872 1302 896">INSPECTOR</p>