

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3749</i>		LOCATION <i>1410 - 55th St.</i>			
DATE <i>9/5/39</i>		PURPOSE <i>New dwls & gar</i>			
ZONE <i>2-7am</i>		OWNER <i>W. Sunther</i>			
		ARCH'T.			
		CONTR. <i>E. Browning</i>			
VAL. <i>2300⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS	SIZE	
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>		
VENT SHAFTS		BOILER ROOMS	<i>1148^{sq} ft</i>		
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 35^{sq}</i>		
LATH		GAS VENTS			
FIRE ESCAPES		CHIMNEYS			
STAND PIPES		SKYLIGHTS			

DATE	CONDITION OF WORK—REMARKS
9-10-37	1st Deep Trench at Pits
7-27-39	2 nd Deep Trench at Pits
10-2-39	3 " " Lark Int. Station Pits
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>