

## BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

|                                |   |  |       |       |      |
|--------------------------------|---|--|-------|-------|------|
| PERMIT NO.<br><b>9875</b>      | LOCATION<br><b>1517-26<sup>TH</sup> ST</b>                |  |       |       |      |
| DATE<br><b>Sept 13 1932</b>    | PURPOSE<br><b>Re-Roof Donly with Composition Shingles</b> |  |       |       |      |
| ZONE<br><b>Mudlapt. Family</b> | OWNER<br><b>MRS. K. YEARGIN</b>                           | <b>1517-26<sup>TH</sup> ST.</b>              |       |       |      |
|                                | ARCH'T  |  |       |       |      |
|                                | CONT-R  | <b>STAR ROOF CO. 1415-5<sup>TH</sup> ST.</b> |       |       |      |
| VAL.                           | <b>186<sup>00</sup></b>                                   | STORIES<br><b>1</b>                          | ROOMS | APTS. | SIZE |
| Light Shafts                   |   | Elevator Shafts                              |       |       |      |
| Vent Shafts                    |   | Boiler Rooms                                 |       |       |      |
| Owner's Inspector              |   | Sprinkler System                             |       |       |      |
| Lath                           |   | Gas Vents                                    |       |       |      |
| Fire Escapes                   |   | Chimneys                                     |       |       |      |
| Stand Pipes                    |   | Skylights                                    |       |       |      |

