

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO: 3862 LOCATION: 89 Herborn Bldg. 2769-25
 PURPOSE: Frk Res - garage ROOMS: 6 APTS.: 1
 DATE: DEC 1, 1928 OWNER: Walson & Bennett PHONE: _____
 ARCH'T: _____
 SACRAMENTO BUILDING DIVISION CONT'R: [Signature]
 VAL.: 5500- STORIES: 1 SIZE: 22x38-21

FOUNDATION	STORY	BSMT	1	2	3	ROOF	Chimneys		Cement Tests
Ex Wall	Jolsts								
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand. Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

12/19/29
1/7/29
1/10/29
1/14/29

DATE	CONDITION OF WORK—REMARKS
12/19/29	1 ST /INSP. FORMS IN PLACE O.K. A.W. Campbell
1/7/29	2 ND /INSP. FRAME IN PLACE O.K. A.W. Campbell
1/10/29	3 RD /INSP. INT. LATH O.K. A.W. Campbell
1/14/29	3 RD /INSP. EXT. LATH O.K. A.W. Campbell

COMPLETED
AND O. K.

INSPECTOR

