

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-11011</i>	LOCATION <i>3217-13-01</i>			
DATE <i>1/2/43</i>	PURPOSE <i>Repairs to dwlg.</i>			
ZONE	OWNER <i>J. R. Pappin</i>			
	ARCH'T. <i>Owner</i>			
	CONTR. <i>Owner</i>			
VAL <i>1500</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
1/19/43	2 <sup>ND</sup> HSP. Frame for enclosing recessed front porch. inc. Window & Door. & changing front steps to end instead of front
	O.K. A W Campbell
	COMPLETE AND O. K.
	INSPECTOR.