



BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 8062	LOCATION Lot 33 South Curtis Oaks 3	2700-10th Ave
DATE MAY 22 1931	PURPOSE Build 2-Story 1-Fam Frame Rustic	PHONES
ZONE 1-Family	OWNER N. H. LUND	
	ARCHT Designer " "	
	CONT-R OWNER	

VAL.	5600⁰⁰	STORIES 2	ROOMS 7	APTS. 1	SIZE 35' x 27'
------	--------------------------	---------------------	-------------------	-------------------	--------------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS	
5/21-31	1 ¹ / ₂ ' Jump Forms OK	P H Rutter
6/10-31	2 " Frame "	P H Rutter
4/12-31	3 " Int Lath "	P H Rutter
8/3-31	4 " Tmaled & OK	Certificate
	of occupancy issued A CE rep	
		
	COMPLETE AND O.K.	 INSPECTOR