

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,237-</i>	LOCATION <i>3318 3324 I St.</i>
DATE <i>4/3/42</i>	PURPOSE <i>Remodel garage for Liv quarters</i>
ZONE <i>—</i>	OWNER <i>Ella G. Campbell</i>
	ARCH'T.
	CON'T.R. <i>Owner</i>

VAL <i>800⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>3</i>	APTS.	SIZE
-----------------------------	------------------	----------------	-------	------

LIGHT SHAFTS	<i>1000⁰⁰ - Owner raised</i>	ELEVATOR SHAFTS	
VENT SHAFTS	<i>Valuation 200⁰⁰ Additional</i>	BOILER ROOMS	
OWNER'S INSPECTOR	<i>for Erecting 1-Car Private</i>	SPRINKLER SYSTEM	
LATH	<i>Garage on rear of lot.</i>	GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/6/42	1 ST /NSP. Cement Floor under Dmg
42 MAY 14	2 ND /NSP. Frame inspected by J. R. Shields
	3 RD /NSP. INT. LATH (5/16" Rocklath)
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>