

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-6 444</i>	LOCATION <i>3417-52nd</i>
DATE <i>9/12/40</i>	PURPOSE <i>Erect new dwg. for</i>
ZONE	OWNER <i>Edw. Healy</i>
	ARCH'T.
	CONT'R. <i>John Loddicks</i>

VAL. <i>4000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area 1100<sup>00</sup> @ 30'</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
9/17-40	1 <sup>st</sup> Insp Formers of Purity
10/9-40	✓ " Frame " Purity
10/14-40	3 " Lark Int " Purity
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="289 993 446 1040">COMPLETE AND O. K.</span> <span data-bbox="1280 1005 1453 1040">INSPECTOR</span> </div>