

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>4-7113-</i>	LOCATION <i>3856 - Stockton Blvd</i>
DATE <i>10/4/37</i>	PURPOSE <i>Repair new trusses</i>
ZONE	OWNER <i>Harold L. Davis</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>700⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="291 860 408 897">COMPLETE AND O. K.</p> <p data-bbox="1079 874 1200 891">INSPECTOR</p>