

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-580</i>	LOCATION <i>Mexico Theater 212 R. Street</i>
DATE <i>May 11-33</i>	PURPOSE <i>Blumberg Gen. Repair & remodel front to theater</i>
ZONE <i>Gen Com</i>	OWNER <i>Blumberg</i>
	ARCH'T <i>A. Greitzer</i>
	CONT-R <i>—</i>

VAL. <i>45⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
---------------------------------------	----------------	--------------	--------------	-------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
	2 nd use Frame for support of Myganski Floor
	supporting Motor, Piston, Machine & Operating
	1-3"x12" supported by 4"x6" Studs and a cross tie at each
	end and 4"x6" supported by 2" Iron Pipe with Flanges
	with 4"x6" on top with 4 x 4 angle Iron with 2-3/4" dia
	supporting end of 3x12 Plank. ^{OK} M. Campbell
	<p data-bbox="329 861 480 909">COMPLETE AND O. K.</p> <p data-bbox="1137 882 1297 909">INSPECTOR</p>