

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3505.</i>	LOCATION <i>609 1/2 St</i>
DATE <i>7/24/39</i>	PURPOSE <i>Repairs &amp; repair stairway</i>
ZONE <i>-</i>	OWNER <i>W. B. Poth</i>
	ARCH'T.
	CONTR. <i>Chas Verina</i>

VAL. <i>5600<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
-------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK--REMARKS
10/3/39	2 <sup>ND</sup> WSP. Frame for Ripper & Interior and Max. Stankman OR Mr. Campbell
10/3/39	3 <sup>RD</sup> WSP. In-liner (Pressure) OR Mr. Campbell
	<p data-bbox="332 1042 478 1091">COMPLETE AND O. K.</p> <p data-bbox="1323 1063 1480 1088">INSPECTOR</p>