

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 2311-A	LOCATION 530 - Pico Way.				
DATE 11/28/34	PURPOSE Const. 6 Rm. Frame Attached Det.				
ZONE 2 - Fam	OWNER C. E. Ruby.				
	ARCH'T Owner				
	CONT'R C. E. Ruby.				
VAL. 5000⁰⁰	STORIES	ROOMS 6	APTS.	See Plans.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
12/4/34	1 ST INSP. FORMS IN PLACE <i>OK</i> <i>AW Campbell</i>
12/18/34	2 ND INSP. PARTIAL FRAME. Only wanted to know if wall separating garage from rest of house is plastered with metal L & P. on both sides - There no metal L & P. required on W + C of garage. Correct <i>AW Campbell</i>
12/27/34	2 ND INSP. BAL. OF FRAME <i>OK</i> <i>AW Campbell</i>
12/31/34	3 RD INSP. EXT LATE IN PLACE <i>OK</i> <i>AW Campbell</i>
1/3/35	3 RD INSP. INT. LATE INC. WALL BKT. DWLG & GARAGE ATTACHED <i>OK</i> <i>AW Campbell</i>
2/19/35	4 TH INSP. DWLG & GARAGE ATTACHED TO DWLG <i>Completed</i> <i>AW Campbell</i>
2/19/35	Issued Final Insp & Cert. of Occ'y. <i>AW Campbell</i> Street cleaned up <i>OK</i>
2/19/35	COMPLETE AND O.K. <i>Allen H Campbell</i> INSPECTOR