

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-13557</i>	LOCATION <i>3426 - Crucker Way</i>			
DATE <i>6/26/45</i>	PURPOSE <i>Erect new dwelling</i>			
ZONE <i>2-Fam</i>	OWNER <i>J. S. Mrs. McKim</i>			
	ARCH'T. <i>O'Connell</i>			
	CONT'R. <i>O'Connell</i>			
VAL. <i>4800<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1200<sup>00</sup></i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
7/2/25	1 <sup>ST</sup> INSP. Frame for New Dr. Est. Garage AW Campbell
8/8/25	2 <sup>ND</sup> INSP. Frame for above <sup>OK</sup> AW Campbell
8/8/25	3 <sup>RD</sup> INSP. EXT. LATH <sup>OK</sup> AW Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="276 854 400 896">COMPLETE AND O. K.</span> <span data-bbox="1084 870 1215 890">INSPECTOR</span> </div>