

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>84722</i>	LOCATION <i>3455 J St.</i>
DATE <i>Aug. 12, 1931</i>	PURPOSE <i>Make General Repairs and Repair Roof of Dory.</i>
ZONE <i>Multiple-Family</i>	OWNER <i>ARDEN W. CAMPBELL, 3455 J. St.</i>
VAL. <i>75⁰⁰</i>	ARCH'T <i>OWNER</i>
STORIES <i>2</i>	ROOMS
APTS.	SIZE

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK-REMARKS
8/15/51	General Repairs & Repainting of Roof of 2-Story Dwelling. A. W. Campbell

COMPLETE
AND O.K.

INSPECTOR