

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-4896</i>	LOCATION <i>760 - Robertson Way</i>			
DATE <i>4/2/41</i>	PURPOSE <i>Erect new dwg w gar</i>			
ZONE	OWNER <i>Anthony Setick</i>			
	ARCH'T.			
	CONT'R. <i>M. H. Fund</i>			
VAL. <i>4500<sup>00</sup></i>	STORIES <i>-</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1283<sup>00</sup></i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 302</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
4/3/41	1 <sup>ST</sup> INSP. Forms in place <sup>OK</sup> A.W. Campbell
5/16/41	2 <sup>ND</sup> INSP. Frame " " <sup>OK</sup> A.W. Campbell
5/21/41	3 <sup>RD</sup> INSP. INT & EXT. LATH <sup>OK</sup> A.W. Campbell
7/15/41	4 <sup>TH</sup> INSP. Drivg & Garage Completed <sup>OK</sup>
7/15/41	<p>COMPLETE AND O. K. <i>Alden W. Campbell</i> INSPECTOR</p>