

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

**TYPE BUILDINGS**

PERMIT NO. <i>9945</i>	LOCATION <i>1541-42<sup>nd</sup> St</i>		
DATE: <i>9-26-32</i>	PURPOSE <i>Re roof dwelling</i>	PHONES	
ZONE	OWNER <i>W. P. Hawthorne</i>	ARCH'T	
VAL. <i>1160<sup>00</sup></i>	CONT-R <i>Superior Lumber &amp; Fuel Co</i>	STORIES	ROOMS
APTS.	SIZE		
<b>Light Shafts</b>	<b>Elevator Shafts</b>		
<b>Vent Shafts</b>	<b>Boiler Rooms</b>		
<b>Owner's Inspector</b>	<b>Sprinkler System</b>		
<b>Lath</b>	<b>Gas Vents</b>		
<b>Fire Escapes</b>	<b>Chimneys</b>		
<b>Stand Pipes</b>	<b>Skylights</b>		

DATE	CONDITION OF WORK--REMARKS
9/27/32	Re Roofing of Roof of Dwyer with Composition Shingles Completed Ald Campbell
9/27/32	COMPLETE AND O. K. Alder H Campbell INSPECTOR