

*R145-1100*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**\$13.00**

**TYPE BUILDINGS**

PERMIT NO. <b>E-7365</b>		LOCATION <b>627 - 42nd Street</b>		A-1	
DATE <b>May 29-64</b>		PURPOSE <b>Const. 1-room &amp; porch to dwelling</b>			
ZONE <b>R-1</b>		OWNER <b>Troy Holt</b>		Same	
		ARCH'T			
		CONTR <b>Robert Lerman 5907 - Ashworth Way</b>			
VAL <b>\$1,100.</b>		STORIES <b>1</b>	ROOMS	APTS. <b>Carm.</b>	SIZE <b>104 sq. ft.</b>
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	<b>6-4-64</b>	<i>Mc Calloway</i>			
JOIST	<b>6-10-64</b>	<i>Mc Calloway</i>			
FRAME	<b>6-26-64</b>	<i>Mc Calloway</i>			
SHEET ROCK	<b>7-1-64</b>	<i>Ruplo</i>			
FINAL	<b>1-25-65</b>	<i>J. Barbato</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
6-30-64	POOR JOB OF NAILING S-ROCK. (Ribs)
7-22-64	P.T. Handrails required - Ribs are
	not uniform Front Porch Balbato
	These requirements were given at
	a previous inspection -
8-11-64	Handrails not installed Balbato

COMPLETE  
AND OK

INSPECTOR