

R-47

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD = 641

**TYPE BUILDINGS**

**\$3.00**

<b>PERMIT NO.</b> C-10002	<b>LOCATION</b> 1000- X Street
	<b>PURPOSE</b> Repair termite damage to dwelling
<b>DATE</b> Oct. 7, 58	<b>OWNER</b> Maurice Slattery
<b>ZONE</b>	<b>ARCH'T</b>
	<b>CONT'R</b> Orchard Supply 1731-17th St. EI 6-7821

<b>VAL.</b> \$250.	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
--------------------	----------------	--------------	--------------	-------------

<b>INSP.</b>	<b>DATE</b>	<b>INSPECTOR</b>
<b>FORM</b>		
<b>JOIST</b>		
<b>FRAME</b>		
<b>LATH</b>		
<b>FINAL</b>		

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK—REMARKS</b>
	<b>COMPLETE AND OK</b>
	<b>INSPECTOR</b>