

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>9559</b>	LOCATION <b>1718 M St.</b>
DATE <b>6/18/32</b>	PURPOSE <b>Rebuild Roof of Dwelling</b>
ZONE <b>Multi</b>	OWNER <b>Mrs E Champlin</b>
	ARCH'T
	CONT-R. <b>W C McMaster</b>

1718 M St.

PHONES

VAL. <b>120-</b>	STORIES	ROOMS	APTS.	SIZE
---------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
6/17/32	Restumping of Roof of Duly completed OK A.W. Campbell
6/17/32	COMPLETE AND O.K. <i>Alden H. Campbell</i> INSPECTOR