

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-6338</i>	LOCATION <i>5978 - 5 Pt.</i>			
DATE <i>5/18/37</i>	PURPOSE <i>Remodel old Bldg.</i>			
ZONE	OWNER <i>E. L. Braman J</i>			
	ARCH'T.			
	CONT'R <i>Owner</i>			
VAL. <i>1000<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK - REMARKS	
5/25-37	1 <sup>st</sup>	Lump Formed on Ructer
6/11-37	2 <sup>d</sup>	Lump Formed on Ructer
6/21-37	3	" Lump on Ructer
1-6-38	4	" <u>Finalled</u> O.K.
	<p>COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span></p>	