

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>906-A</i>	LOCATION <i>1010 - 48th St</i>
DATE <i>9/2/33</i>	PURPOSE <i>Build 12 x 12 addit. to side of</i>
ZONE	OWNER <i>M. L. Shears</i>
	ARCH'T <i>Owner</i>
	CONT-R
	PHONES <i>2111</i>

VAL. <i>750.00</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	



DATE	CONDITION OF WORK-REMARKS
9/4/33	1 st base. Concrete foundation for 1 Base Addition to side of Dory. O.K. R.W. Campbell
9/6/33	2 nd base. Frame for above. O.K. R.W. Campbell
9/7/33	3 rd base. Int. Lath .. O.K. R.W. Campbell
10/15/33	4 th base. Addition to side of Dory. Completed O.K. R.W. Campbell
10/15/33	COMPLETE AND O.K. <i>Arthur W. Campbell</i> INSPECTOR

