

**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

PERMIT NO. <i>1867-A.</i>	LOCATION <i>910 - U Street</i>
DATE <i>7/26/34</i>	PURPOSE <i>Remodeling rear porch well.</i>
ZONE <i>Mult. Fam</i>	OWNER <i>Mr. W. A. Garrett</i>
	ARCH'T <i>L. W. Garner</i>
	CONT'R <i>L. W. Garner</i>

VAL. <i>19000</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
7/30/34	Made Partial Inspection of excavating
	now being done under rear corner of
	Dwelling for Basement. Contractor intends to
	pour concrete footing and build basement
	walls of brick 8" thick. A.W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>