

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4962</i>	LOCATION <i>2694 - Martin Way.</i>			
DATE <i>3/18/40</i>	PURPOSE <i>New duplex apt's</i>			
ZONE	OWNER <i>S. W. Pfeiffer</i>			
	ARCH'T. <i>Paul Osdyke</i>			
	CON'T'R.			
VAL. <i>5000⁰⁰ =</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>124 00'</i>	
VENT SHAFTS		BOILER ROOMS	<i>@ 372</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
3/11/40	1 st / N.S.P. Formed in place of ^{of} R.W. Campbell
3/26/40	2 nd / N.S.P. Formed ^{of} R.W. Campbell
	<p data-bbox="288 844 425 885">COMPLETE AND O. K.</p> <p data-bbox="1138 859 1275 885">INSPECTOR</p>