

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5553-</i>	LOCATION <i>1531 ~ PRT.</i>
DATE <i>11/19/37-</i>	PURPOSE <i>Const super-service stat.</i>
ZONE	OWNER <i>(Celia Kelafos) Richfield Oil Co</i>
	ARCH'T.
	CONTR. <i>Wm Trussdale</i>

VAL. <i>65,000</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
1/27/37	<p>1st / N.S.P. Concrete Footing for Steel Guts for New Re Constructed All-Steel Service Station + Rest Room O.K. A.W. Campbell</p>
4/9/37	<p>2nd / N.S.P. Steel Frames for Above ^{O.K.} A.W. Campbell Note - No Lathing or Plastering included in work A.W.C.</p>
1/37	<p>4th / N.S.P. Re Constructed Service Station Complete O.K. A.W. Campbell</p>
1/37	<p>COMPLETE AND O. K. <i>A.W. Campbell</i> INSPECTOR</p>