

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>8068</b>	LOCATION <b>217-32<sup>ND</sup> ST.</b>			
DATE <b>MAY 22 1931</b>	PURPOSE <b>Build 14'x21' Addition to Rear of Dwg. for Sleeping + Screen Porch.</b>			
ZONE <b>2-Family</b>	OWNER <b>CHARLES GILES</b>			
	ARCH'T <b>J. D. HAWORTH</b>			
	CONT-R <b>J. D. HAWORTH</b>			
VAL. <b>500<sup>00</sup></b>	STORIES <b>1</b>	ROOMS	APTS. <b>1</b>	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
5/1-31	1 <sup>st</sup> Runp Forms in place OK P.H. Winter
6/27/31	2 <sup>ND</sup> /NSP. Frame (PARTIAL) A.W. Campbell
	Note Fire Strips not in. 2 openings not crossed over
A.M.	Prof. Rafting not all supported. A.W. Campbell
P.M. 6/29/31	2 <sup>ND</sup> /NSP. Frame now OK A.W. Campbell
6/30/31	3 <sup>RD</sup> /NSP. INT. LATH OK A.W. Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="331 854 494 906">COMPLETE AND O.K.</span> <span data-bbox="1168 875 1337 906">INSPECTOR</span> </div>