

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. <i>No Charge</i>	LOCATION <i>Service Station 1930 J. St</i>
DATE <i>June 7th 1930</i>	PURPOSE <i>Change 2 Blind Pumps to Visible Pumps and Install</i>
ZONE <i>General Residential</i>	OWNER <i>UNION OIL Co Hydraulic Dept.</i>
	ARCH'T
	CONT'R <i>Owner</i>

VAL. <i>500⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
---------------------------------	---------------------	-------	-------	------

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="313 860 471 905">COMPLETED AND O.K.</p> <p data-bbox="1144 886 1288 905">INSPECTOR</p>