

R205 F115

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00**

**TYPE BUILDINGS**

**DOUBLE FEE**

<b>PERMIT NO.</b> F-5597		<b>LOCATION</b> 4000 - San Carlos Way		A-4	
<b>DATE</b> Oct 12-66		<b>PURPOSE</b> Repair termite damage to dwelling			
<b>ZONE</b> R-1		<b>OWNER</b> Stella Zaidel same			
		<b>ARCH'T</b>			
		<b>CONT'R</b> Dale's Termite 4343-Marconi 483-5386			
<b>VAL.</b> \$300.		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>	8-13-67	Dana Fuller			

0.27

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
11/2/66	Pt Final - Refurnish. Replumbing. Repair
COMPLETE AND OK	INSPECTOR