

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>B-1810</b>	LOCATION <b>1216 - 64<sup>th</sup> Street</b>
DATE <b>10/25/38</b>	PURPOSE <b>Erect new dwlg. &amp; gar.</b>
ZONE <b>2-Fam</b>	OWNER <b>C. L. Lunkford</b>
	ARCH'T.
	CONT'R. <b>Owner</b>

VAL. <b>2500<sup>00</sup> =</b>	STORIES <b>1</b>	ROOMS	APTS.	SIZE
---------------------------------	---------------------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<b>761<sup>12</sup> @ 350</b>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
11-1-38	18' Deep Foundation at Route
12/19/38	2' " Foundation at Route
	<p data-bbox="320 997 472 1039">COMPLETE AND O. K.</p> <p data-bbox="1320 1012 1471 1036">INSPECTOR</p>