

R330F87

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$6.00

TYPE BUILDINGS

| | | | | | |
|---------------|---------------------------------------|------------|-----------------|---------------|--|
| PERMIT NO. | LOCATION | | | | |
| H-7338 | 1501 - 28th Street A-2 (13) | | | | |
| DATE | PURPOSE | | | | |
| June-1-72 | Const. shaft for air-conditioning in | | | | |
| ZONE | OWNER | | | | |
| | Jack D. Phillips /apt. & retail store | | | | |
| | ARCH'T | | | | |
| | CONTR | | | | |
| | Owner | Same | 881 - San Ramon | | |
| VAL. \$100. | STORIES | ROOMS | APTS. | SIZE | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | | | F-2 H | | |
| JOIST | | | | | |
| FRAME | | | | | |
| SHEET ROCK | | | | | |
| FINAL | 4/8/75 | J. Balbato | | | |

| DATE | SPECIAL CONDITIONS OF WORK --- REMARKS |
|--------------------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND OK | INSPECTOR |

