

Roller E 114

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$6.00

TYPE BUILDINGS

| | | | | | |
|-------------|---------------|--|-----------------|-------|---------------|
| PERMIT NO. | | | | | |
| H-4518 | | LOCATION 3887 - 9th Avenue A-1 (28) | | | |
| DATE | | PURPOSE Repair porch and floor of dwelling per | | | |
| Dec. 2-71 | | OWNER E. B. Davenport P.O. Box 285 /Housing | | | |
| ZONE | | ARCH'T | | | |
| R-1 | | CONTR Owner Auburn Calif. 885 9450 | | | |
| VAL. \$500. | | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | | PHONE (O) (C) |
| FORM | | | | | |
| JOIST | | | | | |
| FRAME | | | | | |
| SHEET ROCK | | | | | |
| E.C. FINAL | <i>3-8-74</i> | <i>E. B. Davenport</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|-------------|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR