

## BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>9882</b>		LOCATION <b>1819-11<sup>th</sup> St</b>			
DATE <b>Sept 15 1932</b>		PURPOSE <b>Tear Out &amp; Rebuild Bath Room &amp; Storage Room on 2nd Floor</b>		PHONES <b>Long Florida</b>	
ZONE <b>General Commercial</b>		OWNER <b>G. H. LAWRENCE, 1819-11<sup>th</sup> St</b>			
		ARCH'T <b>SILLER BROS</b>			
		CONT-R <b>SILLER BROS</b>			
VAL. <b>600<sup>00</sup></b>		STORIES <b>2</b>	ROOMS <b>2</b>	APTS. <b>2</b>	SIZE
Light Shafts		Elevator Shafts			
Vent Shafts		Boiler Rooms			
Owner's Inspector		Sprinkler System			
Lath		Gas Vents			
Fire Escapes		Chimneys			
Stand Pipes		Skylights			

DATE	CONDITION OF WORK--REMARKS
9/21-30	2 <sup>nd</sup> Insp Frame OK R.H. Jones
	COMPLETE AND O. K. INSPECTOR