

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD.

TYPE BUILDINGS

| | | | |
|--|----------------------------------|---|--------|
| PERMIT NO. <i>A-548</i> | LOCATION <i>1463-46th St.</i> | PURPOSE <i>Alteration - Repair to Dwelling</i> | PHONES |
| DATE <i>Apr. 28th 33</i> | OWNER <i>G. E. Wright</i> | ARCH'T | |
| ZONE <i>1-Fam.</i> | CONT-R <i>Owner-</i> | | |

| | | | | |
|------------------------------|---------|-------|-------|------|
| VAL. <i>350⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
|------------------------------|---------|-------|-------|------|

| | | | |
|-------------------|--|------------------|--|
| Light Shafts | | Elevator Shafts | |
| Vent Shafts | | Boiler Rooms | |
| Owner's Inspector | | Sprinkler System | |
| Lath | | Gas Vents | |
| Fire Escapes | | Chimneys | |
| Stand Pipes | | Skylights | |

| DATE | CONDITION OF WORK—REMARKS |
|---------|--|
| 4/28/33 | <p>Made Preliminary Inspection of proposed alterations to Dairy. Attached Garage on south side to be altered for Dairy Room & Breakfast Room etc. New 2 Stall P.M. Garage having already been erected on rear of lot recently.</p> <p style="text-align: right;">M. Campbell</p> |
| 5/2/33 | <p>2nd insp. Frame in above OK M. Campbell</p> |
| | <p style="text-align: center;">COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p> |