

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

<b>PERMIT NO.</b> B-19857	<b>LOCATION</b> 2200 - 4 <sup>th</sup> Ave
<b>DATE</b> 10/30/44	<b>PURPOSE</b> Re-roof dwlg comp
<b>ZONE</b> —	<b>OWNER</b> G. J. White
	<b>ARCH'T.</b>
	<b>CONTR.</b> Walsh Roofing Co.

<b>VAL.</b> 25600	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
-------------------	----------------	--------------	--------------	-------------

<b>LIGHT SHAFTS</b>		<b>ELEVATOR SHAFTS</b>	
<b>VENT SHAFTS</b>		<b>BOILER ROOMS</b>	
<b>OWNER'S INSPECTOR</b>		<b>SPRINKLER SYSTEM</b>	
<b>LATH</b>		<b>GAS VENTS</b>	
<b>FIRE ESCAPES</b>		<b>CHIMNEYS</b>	
<b>STAND PIPES</b>		<b>SKYLIGHTS</b>	

<b>DATE</b>	<b>CONDITION OF WORK—REMARKS</b>
	<p data-bbox="332 984 483 1030"><b>COMPLETE AND O. K.</b></p> <p data-bbox="1323 1007 1481 1030"><b>INSPECTOR</b></p>