

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4799</i>	LOCATION <i>3727 - 39<sup>th</sup> Street</i>			
DATE <i>2/7/37</i>	PURPOSE <i>Erect new dwlg = detached garage</i>			
ZONE <i>2-Fam.</i>	OWNER <i>F. H. Nicklin</i>			
	ARCH'T.			
	CONTR. <i>C. P. Ruby</i>			
VAL <i>3000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE <i>Per Plans</i>

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i> <i>954<sup>sq</sup> ft</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
2-17-38	1 <sup>st</sup> Leap Form on Rutter
3/10. 38	2 " Travel " Rutter
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="337 806 472 847">COMPLETE AND O. K.</span> <span data-bbox="1187 819 1328 847">INSPECTOR</span> </div>