

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-2727</i>	LOCATION <i>1704 - 4 St.</i>		
DATE <i>4/23/35</i>	PURPOSE <i>To exist, small bldg for store</i>	PHONES	
ZONE <i>Gen Com</i>	OWNER <i>John Mentz</i>		
	ARCH'T <i>Eugene Peadler</i>		
	CON'T'R <i>F. H. Carter</i>		
VAL. <i>2850⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.
			<i>40 x 40</i> SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
4/29/35	1 ST /INSP. Footings In Brick Store Bldg. OK NW Campbell
5/5/35	2 ND /INSP. FRMF. Contractor changed return of Brick Walls at rear from 3'4" x 5'4" as per Code. NW Campbell
5/17/35	3 RD /INSP. INT. & EXTERIOR OK NW Campbell
5/29/35	4 TH /INSP. Store Bldg. completed OK Stairs cleaned up OK
5/29/35	COMPLETE AND O.K. <i>(NW Campbell)</i> INSPECTOR