

8137 2456-460

Lt. 21

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$34.00

Blk 8

TYPE BUILDINGS

Avondale #1

| | | |
|-----------------------------|---------------------------------------------------------|--------------------------|
| PERMIT NO. E-6308 | LOCATION 5971 - 79th Street | A-4 |
| DATE Feb. 24-64 | PURPOSE Const. dwelling & attached garage | |
| ZONE R-1 | OWNER Hosie Houston | 5920-Wallace Ave. |
| | ARCH'T | |
| | CONT'R Owner | Same 457-5948 |

| | | | | | |
|----------------------|---------------------|-------------------|-------|-------------------|------|
| VAL. \$8,900. | STORIES 1 | ROOMS 5 | APTS. | 336-gar. | SIZE |
| | | | | 910 sq.ft. | |

| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
|------------|----------------|---------------|-----------------|---------------|
| FORM | <i>2-25-64</i> | <i>Conrt</i> | | |
| JOIST | <i>3-6-64</i> | <i>Rislo</i> | | |
| FRAME | <i>5/15/64</i> | <i>Rislo</i> | | |
| SHEET ROCK | <i>5/28/64</i> | <i>Blk 8</i> | | |
| FINAL | <i>3-11-65</i> | <i>Fuller</i> | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|------------------------------------------------------------------|
| 12-1-64 | not complete <i>E. Larson</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK INSPECTOR |