

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS *R17-F-173-184*

PERMIT NO. <i>7468</i>	LOCATION <i>3842 J Street</i>	PHONES
DATE <i>10/1/50</i>	PURPOSE <i>Par Church, Par V Parish the General Assembly</i>	
ZONE <i>Man</i>	OWNER <i>Roman Catholic Church</i>	
	ARCH'T <i>Henry Devereux</i>	
	CONTR <i>W.C. Keating</i>	

VAL. <i>94000</i>	STORIES <i>1-4</i>	ROOMS <i>15</i>	APTS.	SIZE <i>33 x 106-00</i> <i>2700 sq ft</i>
----------------------	-----------------------	--------------------	-------	---

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS
12/18/30	Preliminary Insp. Contract, now excavate, with power shovel, + hauling dirt away. <sup>OK</sup> H. W. Campbell
1/12/31	1 <sup>st</sup> Insp. Features for Retaining Pier + Wall. <sup>OK</sup> H. W. Campbell
1/14/31	1 <sup>st</sup> " " Re-Inf. C.U. + 1 <sup>st</sup> Basement Wall to Retaining Wall. <sup>OK</sup> H. W. Campbell
2/2/31	1 <sup>st</sup> " " Features for " (South Side) <sup>OK</sup> H. W. Campbell
3/21/31	2 <sup>nd</sup> Insp. Frame on Parish House. <sup>OK</sup> H. W. Campbell
2/2/31	3 <sup>rd</sup> Insp. Church House Metal and Roof work. <sup>OK</sup> H. W. Campbell
6/9/31	2 <sup>nd</sup> Insp. Frame on Main Church Bldg. <sup>OK</sup> H. W. Campbell
6/16/31	3 <sup>rd</sup> Insp. Int. Metal Work in Church Bldg. <sup>OK</sup> H. W. Campbell
	<p data-bbox="329 857 486 903">COMPLETED AND O.K.</p> <p data-bbox="1176 888 1318 909">INSPECTOR</p>