

BUILDING DIVISION BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 7693	LOCATION 2901 O St.			
DATE: 7/22/37	PURPOSE <i>install</i> <i>Permit, 2nd Garage under 1st - In Rep</i>		PHONES	
ZONE <i>Mult</i>	OWNER <i>Ch. Christensen</i>			
	ARCH'T			
	CONT-R <i>Pease, Mykenney + Leach</i>			
VAL. <i>575</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
7/22/32	Notified Owner to get this Permit for Re-Roofing Dwlg with Composition Shingles. Also for installing private garage under Dwlg with metal lath and plaster Walls & Ceiling: A.W. Campbell
8/27/32	Notified Owner private garage must be fireproofed. Owner asked for extension of time as he was short of funds A.W.C. Property changed hands.
1/19/34	Notified Neville & Tracy. Asks fireproofing had not been done. Should write him a letter accordingly.
	COMPLETE AND O. K. INSPECTOR