

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS *R1-F-527-532*

PERMIT NO. <b>B-36551</b>	LOCATION <b>317 33rd Street</b>			
DATE <b>11-3-52</b>	PURPOSE <b>Erect meeting hall</b>			
ZONE	OWNER <b>United steel workers of America</b>			
	ARCH'T.			
	CON'T'R, <b>Opdyke and Butler</b>			
VAL. <b>\$11,400.00</b>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
11-14-52	Form Dow Boring
11-21-52	First Bond Beam steel. Dow Boring.
12-2-52	Bond Beam South wall steel Dow Boring.
3-3-53	Final " "
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>

11-14-52  
 11-21-52  
 12-2-52  
 3-3-53