


**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE VII BUILDINGS**

PERMIT NO. <b>4812</b>	LOCATION <b>1872 Healdsburg Oaks - 5700-56 1/2 St.</b>	
	PURPOSE <b>FRN Res. Garage</b>	ROOMS <b>2</b>
DATE <b>ISSUED</b>	OWNER <b>G. Kiant 11229</b>	APTS. <b>1</b>
ZONE <b>1929</b>	ARCHT <b>Jos Pedone</b>	PHONE
SACRAMENTO BUILDING DIVISION	CONTR <b>Jos Pedone 9142</b>	
	VAL. <b>6000-</b>	STORIES <b>1</b>
		SIZE <b>37 x 60 - 20</b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	



DATE	CONDITION OF WORK—REMARKS
7/17/29	1 <sup>st</sup> / NSP. Forms in Place + OK P. H. Reuter
7/24/29	2 <sup>nd</sup> / NSP. Frames " " " P. H. Reuter
7/26/29	3 <sup>rd</sup> / NSP. Ext Lath " " " P. H. Reuter
7/28/29	4 <sup>th</sup> / Insp Finald 4 Certificates of Occupancy Issued, OK
	<p data-bbox="339 816 485 857">COMPLETED AND O. K.</p> <p data-bbox="521 782 978 877">P. H. Reuter</p> <p data-bbox="1088 837 1228 857">INSPECTOR</p>

