

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-1301</i>	LOCATION <i>3092-20th St</i>
DATE <i>1/8/34</i>	PURPOSE <i>Add to garage</i>
ZONE <i>1</i>	OWNER <i>E. O. Strong</i>
	ARCH'T <i>Quincy</i>
	CONT-R <i>-</i>
	PHONES

VAL. <i>125⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE <i>12x20</i>
------------------------------	---------	-------	-------	----------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
1/12/34	1 ST /NSP. Cement Floor for 1 st Skill (Poi) Garage built immediately at rear of present
	O.K. A.W. Campbell
1/26/34	2 ND /NSP. Frame for above ^{O.K.} A.W. Campbell
2/8/34	3 RD /NSP. INT & EXT LATH ON GARAGE WALL ON LINE O.K. A.W. Campbell
2/19/34	4 TH /NSP. Addition to rim of Poi Garage Completed
2/19/34	COMPLETE AND O. K. <i>Alden H. Campbell</i> INSPECTOR