

*RB 7127-28*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$16.00

**TYPE BUILDINGS**

PERMIT NO. <b>E-558</b>	LOCATION <b>5049 - 9th Avenue</b> <b>A-1</b>				
DATE <b>Feb. 2-62</b>	PURPOSE <b>Add room &amp; patio, repair fire damage</b>				
ZONE <b>R-1</b>	OWNER <b>Gilbert Steinhaus</b> to dwelling.				
	ARCH'T				
	CONTR <b>Owner Same GL 5-5858</b>				
VAL. <b>\$2,800.</b>	STORIES <b>1</b>	ROOMS	APTS.	160-patio SIZE <b>276 sq.ft.</b>	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP		
FORM	<i>8-10-62</i>	<i>Barbato</i>	<i>9-4-62 Barbato</i>		
JOIST	<i>9-62</i>	<i>Barbato (partial)</i>	<i>9-4-62 Barbato</i>		
FRAME	<i>11-5-63</i>	<i>Collins</i>			
SHEET ROCK	<i>11-5-63</i>	<i>Collins</i>			
FINAL					

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
2-7-62	OK to install ceiling joists <i>Fuller</i>
3-28-62	From the plans on job <i>Fuller</i> Couldn't tell what was going on
2-8-63	No one home. Not ready for frame. 1-23-28-63 <i>Harve.</i>
3-28-63	Kept note for owner to contact me & explain why no progress <i>Harve.</i>
6-22-63	Still working 10-22-63 <i>Fuller</i>
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="302 847 429 902">COMPLETE AND OK</span> <span data-bbox="1147 878 1282 902">INSPECTOR</span> </div>