

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE VII BUILDINGS**

<b>PERMIT NO.</b> <i>NO CHARGE</i>	<b>LOCATION</b> <i>2200 P St.</i>		
<b>DATE</b> <i>Dec. 12 1930</i>	<b>PURPOSE</b> <i>Make Repairs to Front Porch.</i>	<b>ROOMS</b>	<b>APTS.</b>
<b>ZONE</b> <i>Multiple Family</i>	<b>OWNER</b> <i>MRS GILFILLAN</i>	<b>PHONE</b>	
	<b>ARCH'T</b>		
	<b>CONT'R</b> <i>D. TATTI.</i>		
	<b>VAL.</b> <i>50.00</i>	<b>STORIES</b> <i>2</i>	<b>SIZE</b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
<b>EX WALL</b>	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
<b>Int Wall</b>	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
<b>Piers</b>	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
4/12/34	<p>Made inspection of repairs now being made to front porch. Butters Walk above porch floor being poured with concrete in old forms &amp; removed later and cement finished later.</p> <p style="text-align: right;">O.K. H.W. Campbell</p>
	<p style="text-align: center;">COMPLETED AND O.K.</p> <p style="text-align: right;">INSPECTOR</p>