

Lot #13 BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$31.00

Plat of Avondale #1 **TYPE BUILDINGS** *R 90 7149-151*

PERMIT NO. D-9746	LOCATION	5631 - 79th Street	A-4
DATE Oct. 10-61	PURPOSE	Const. dwelling & attached garage.	
ZONE R-1	OWNER	Louis Montoya	5641 - 79th St.
	ARCH'T	IV 3-8155	
	CONT'R	Wilmar Investor Devel. 4320-Orange Grove Ave	

VAL. \$10,100.	STORIES 1	ROOMS 5	APTS.	SIZE 1,066 sq.ft.
----------------	--------------	------------	-------	----------------------

INSP.	DATE	INSPECTOR
FORM	<i>10-31-61</i>	<i>Conant</i>
JOIST	<i>Concrete</i>	
FRAME	<i>Wood</i>	
LATH	<i>2-3-7-62</i>	<i>Reals</i>
FINAL	<i>6-12-62</i>	<i>Dana Fuller</i>

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
------	------------------------------------

11-22-61 Pt Frame: Exterior plates not checked.

Mount in gow (Empress) furnished since
 wire not correctly mailed Fuller
 Pt Frame: Gov. Firwall not properly

12-6-61 blocked mud sill & rot. adu plate
 not banded & shot properly Court

12-19-61 Pt SR Out. identified. Project cost
 shows no framing Barlow

Frame signed by Court. Left Red

2-8-62 No. to mail SR & call for miss Fuller

3-31-62 Pt frame, firwall Callaway

5-24-62 Nails not spotted in firwall Fuller
 notice sent 10-4-62

6-7-62 COMPLETE AND OK Pt frame Firwall nails not spotted Inspector
 Fuller