

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE VII BUILDINGS**

<b>PERMIT NO.</b> 6999	<b>LOCATION</b> 1615-23 <sup>rd</sup>		
<b>DATE</b> 9/23/20	<b>PURPOSE</b> Renov	<b>ROOMS</b>	<b>APTS.</b>
<b>ZONE</b> Multiple Family	<b>OWNER</b> K Bankers		<b>PHONE</b>
	<b>ARCH'T</b>		
	<b>CONT'R</b> Star Renov Co		
	<b>VAL.</b> 162	<b>STORIES</b>	<b>SIZE</b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF			
Ex Wall	Joints						Chimneys		Cement Tests
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
9/24/30	Re-Roofing of Dory with Composition Shingles completed O.K. A.W. Campbell,
	<del></del>
9/24/30	COMPLETED AND O.K. <i>Alden W Campbell</i> INSPECTOR